

# Oil Field Environmental Incident Summary

**Incident:** 20151110160808

**Date/Time of Notice:** 11/10/2015 16:08

**Responsible Party:** Kevin Jacob

**Well Operator:** WHITE OWL ENERGY SERVICES (US) INC.

**Well Name:** W.O. Watford #1

**Field Name:** SIVERSTON

**Well File #:** 90172

**Date Incident:** 11/10/2015

**Time Incident:** 06:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 150

**Rng:** 98

**Sec:** 22

**Qtr:** NE SW

**Location Description:**

**Submitted By:** Kevin Jacob

**Received By:**

**Contact Person:** Kevin Jacob

12271 26F St NW

Watford City, ND 58854

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 999 Feet

**Distance Nearest Water Well:** 500 Feet

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	barrels	3	barrels		
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

salt water absorption into skin

**Areal Extent:**

Approximately 10 square feet

**Potential Environmental Impacts:**

soil, scoria and rock were contaminated

**Action Taken or Planned:**

The disposal operator immediately shut the injection pump down to stop the incident. The standing saltwater was sucked up by a vacuum tractor/trailer. The contaminated soil, scoria and rock was picked up using a skid steer and shovels and placed into a steel waste bin. A trucking company will be on site Wednesday morning 11/11/15 to haul off contaminated scoria, rock and soil.

**Wastes Disposal Location:** The recovered waste will be hauled to a solid waste disposal on 11/11/15.

**Agencies Involved:****Updates**

**Date:** 11/10/2015 **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to equipment failure, remained on the facility site according to the report. NDIC retains oversight.